

**ALTRA UNITA' IMMOBILIARE**  
**NON OGGETTO D'INTERVENTO**

**VIA NAVATE**

**ALTRA PROPRIETA'**

**LIMITE D'INTERVENTO**

Dimensions and setbacks shown on the plan:

- Top setbacks: 1.00, 1.20, 1.00, 1.20, 1.00, 1.20
- Right setbacks: 13.54, 13.22
- Bottom setbacks: 6.52, 6.52, 6.20
- Left setbacks: 5.20, 0.00
- Internal dimensions: 3.64, 0.95, 2.10, 0.16, 2.00, 1.50, 1.50
- Other dimensions: 5.85, 20.30, 5.31, 6.52, 6.20

**VIA NAVATE**

1.25 3.69 10.04 3.17 10.30  
1.00 0.25 1.00 1.00 1.00 1.00 12.27

CAMERA 2  
Sup. Pav. 11,29 mq  
Sup. Fin. 1,60 mq  
R.A.I. 0,141 > 0,125

BAGNO 1  
Sup. Pav. 5,78 mq  
Sup. Fin. 1,90 mq  
R.A.I. 0,278 > 0,125

CAMERA 3  
Sup. Pav. 12,80 mq  
Sup. Fin. 1,60 mq  
R.A.I. 0,143 > 0,125

ATRIO  
Sup. Pav. 3,74 mq

CABINA ARMADIO  
Sup. Pav. 5,97 mq

CAMERA 1  
Sup. Pav. 19,76 mq  
Sup. Fin. 1,50+1,50 mq  
R.A.I. 0,152 > 0,125

ALTRA UNITA' IMMOBILIARE

NON OGGETTO D'INTERVENTO

VUOTO SU PIANO TERRA

0.00

2.00 2.86 1.00 1.00 1.00 1.00 6.86

**VIA NAVATE**



- PIANO DI RECUPERO: Convenzione urbanistica del 13.11.95 Rep.53585 Notaio Conti
- DIA prot.4128 del 27/06/2014 "Manutenzione straordinaria copertura";

Architectural elevation drawing of a building facade. The drawing shows a tiled roof, a central entrance with a yellow door, and a large window on the right. Vertical red dashed lines mark the 'LIMITE D'INTERVENTO' (Intervention Limit) and 'LIMITE DI PROPRIETA' (Property Limit). The text 'ALTRA PROPRIETA'' (Other Property) is on the left, and 'VIA NAVATE' is on the right.

